

Release Notes for Armada Components.

2.15:

If you have Errors in linking older apps to new toolsets installed in Borland

[Linker Error] Unresolved external 'HwSetLicenseKey' referenced from C:\PROGRAM FILES\BORLAND\CBUILDERS\PROJECTS\LIB\IIMATADORPKG6.LIB\MatadorDriverIntf.cpp

[Linker Error] Unresolved external 'HwNewDevice' referenced from C:\PROGRAM FILES\BORLAND\CBUILDERS\PROJECTS\LIB\IIMATADORPKG6.LIB\MatadorDriverIntf.cpp

[Linker Error] Unresolved external 'HwConnectDevice' referenced from C:\PROGRAM FILES\BORLAND\CBUILDERS\PROJECTS\LIB\IIMATADORPKG6.LIB\MatadorDriverIntf.cpp

[Linker Error] Unresolved external 'HwGetBusDataByOffset' referenced from C:\PROGRAM FILES\BORLAND\CBUILDERS\PROJECTS\LIB\IIMATADORPKG6.LIB\MatadorDriverIntf.cpp

[Linker Error] Unresolved external 'HwDeleteDevice' referenced from C:\PROGRAM FILES\BORLAND\CBUILDERS\PROJECTS\LIB\IIMATADORPKG6.LIB\MatadorDriverIntf.cpp

[Linker Error] Unresolved external 'HwReadDeviceExtension' referenced from C:\PROGRAM FILES\BORLAND\CBUILDERS\PROJECTS\LIB\IIMATADORPKG6.LIB\MatadorDriverIntf.cpp

[Linker Error] Unresolved external 'HwWriteDeviceExtension' referenced from C:\PROGRAM FILES\BORLAND\CBUILDERS\PROJECTS\LIB\IIMATADORPKG6.LIB\MatadorDriverIntf.cpp

[Linker Error] Unresolved external 'HwConnectDeviceInterrupt' referenced from C:\PROGRAM FILES\BORLAND\CBUILDERS\PROJECTS\LIB\IIMATADORPKG6.LIB\MatadorDriverIntf.cpp

[Linker Error] Unresolved external 'HwDisconnectInterrupt' referenced from C:\PROGRAM FILES\BORLAND\CBUILDERS\PROJECTS\LIB\IIMATADORPKG6.LIB\MatadorDriverIntf.cpp

Add this line to the ApplicationForm.cpp where the II components have been placed.
#pragma link "IIDriverX6"

This new package was not in the older toolsets. All new applications will have this line automatically installed.