

Code Composer Studio v 3.x

Status as of October '04

1. Due to compiler and linker defects, Innovative Integration recommends that customers NOT use release 3.x of CCStudio with our DSP boards. We hope for resolution in some upcoming release, but have received no firm commitments from TI. TI has received our bug submissions and acknowledges the defects.
2. Current JTAG driver distribution (Code Hammer v 1.3.0.0, released 8/18/04, CD version 3.50 and above) does support CCS 3.x and CCS 2.x. The new driver and IIPciPod.DLL is backward compatible. The CodeHammer6x.exe installation program automatically detects Code Composer 3.x or 2.x and installs the driver files accordingly into either or both environments.
3. For new devpacks being sold, Innovative Integration will continue to include CCS2.x until version 3.x is improved and tested successfully in house.